

Laser Machines
GravoCare Service Fixed Rate



Lasers, just like any other machines, require regular maintenance and service. To increase its working life, your laser should be:

- kept clean (use a quality fume extraction system, clean the laser regularly, check lenses and mirrors daily)
- protected against humid environment as well as sudden temperature changes
- used regularly (avoid leaving source inactive for long periods of time as it loses its efficiency)
- serviced on a yearly basis

GravoCare Service Laser Machines

GravoCare Service details - C02 laser:

1. Inspect and clean mirrors & lenses
2. Inspect belts and carriage
3. Check and clean filters, fans, extraction system & air assist
4. Check laser source power output and consistency
5. Check condition of bearings and bearing supports
6. Check machine alignment and focusing
7. Inspect leadscrews for wear
8. Upgrade machine boot / firmware if required
9. Lubricate and clean machine (*)
10. Carry out quality lasering check

GravoCare Service details - YAG laser:

1. Inspect and clean all visible optics
2. Inspect and clean laser module (fans & casing)
3. Inspect and clean control unit & housing (*)
4. Check error message history log & clear
5. Check laser power output at following:
 - a. fibre output
 - b. laser module output
 - c. galvo scanner head
6. Update / upgrade software or firmware (where applicable)
7. Quality marking test

(*) in the case of an exceptionally dirty machine there will be an option to pay for extra cleaning

Benefits of GravoCare Service

To ensure that machine remains fully operational - preventive maintenance minimises risks of breakdown
To help maintain the value of machine thanks to regular maintenance (service report will be provided)
Service rate is fixed in advance - no surprises

Any additional work will be quoted separately. No parts will be replaced without customer's prior agreement
If additional parts need to be fitted and the labour for completing this work is minimal no additional labour will be charged
If the work required is more complex a separate labour charge will be quoted by the engineer

	Return to base	On site Zone 1	On site Zone 2	On site Zone 3	On site Zone 4
GravoCare Service Fixed Rate Tariff - C02	£180	£310	£365	£445	£495
GravoCare Service Fixed Rate Tariff - YAG	£210	£340	£395	£475	£525

Machine must be easily accessible from all sides as well as underneath. Additional labour charges may otherwise occur

Zone definition

Zone 1: Mainland UK (exclusions below)
 Zone 2: Central London, Wales, N. Yorkshire, Cumbria, Co. Durham, Tyne & Tees, Northumberland, Scotland Zone 2
 Zone 3: Devon, I. of W., Scotland Zone 3
 Zone 4: Cornwall, Northern Ireland, Scotland Zone 4
Other charges such as congestion charge, ferries, etc will be charged at cost
Isle of Man, Scottish Islands and other islands - prices on request.

Return to base Machine to be sent to our Leamington Spa workshop. We can organise chargeable collection if required
Return carriage will be charged at a cost dependent upon machine

Contact details

Direct Line 01926 884433 option 3
 Fax 01926 886961
 E-mail support@gravograph.co.uk